

V1.4.17.1


Release Notes	
Status	HOTFIX
Release Date	2015-04-07
Summary	This is a bugfix release

Changes in this version		
T	Key	Summary
	NXBSL-100	Firmware validation does not work when using SQIROM (netX10/51/52) no security memory is present and tag list entries shall be used

1 issue

Known Issues					
T	Key	Summary	Fix Version/s	Status	Resolution
	NXBSL-120	Disable I2C SCL during startup of BSL	V1.6.0.1	RESOLVED	Fixed
	NXBSL-107	Serial flash detection does not work, if flash is in wrong state at startup	V1.4.18.0	CLOSED	Fixed
	NXBSL-52	netX10/51: Winbond Flashes need a reset command to exit SQI mode, which is not passed in boot tokens	V1.4.18.0	CLOSED	Fixed

3 issues

Downloads	
Binaries:	
File	Modified ▲
›  SSBL_LFW_V1.4.17.1.zip Second Stage Bootloader V1.4.17.1 - Binaries	2015-04-07 by Michael Trench