


V1.5.2.0


Release Notes	
Status	RELEASE
Release Date	2018-07-11
Summary	This is a new feature release

Changes in this version		
T	Key	Summary
	NXBSL-116	Adjust the Slot Number function to work with new CIFX-CCLIES PC card

1 issue

Known Issues					
T	Key	Summary	Fix Version/s	Status	Resolution
	NXBSL-120	Disable I2C SCL during startup of BSL	V1.6.0.1	RESOLVED	Fixed
	NXBSL-117	Refactoring of flash detection	V1.6.0.0	CLOSED	Fixed

2 issues

Downloads	
Binaries:	
File	Modified ▲
▶  SSBL_LFW_V1.5.2.0.zip Second Stage Bootloader V1.5.2.0 - Binaries	2018-07-11 by Robert Mayer