

V1.6.0.1


Release Notes	
Status	HOTFIX
Release Date	2019-03-25
Summary	This is a bugfix release

Changes in this version		
T	Key	Summary
	NXBSL-120	Disable I2C SCL during startup of BSL

1 issue

Known Issues					
T	Key	Summary	Fix Version/s	Status	Resolution

No issues found

Downloads	
Binaries:	
File	Modified [▲]
 SSBL_LFW_V1.6.0.1.zip Second Stage Bootloader V1.6.0.1 - Binaries	2019-03-25 by Alexander Minor